


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 50 Watt max. and use a pencil tip.
- 4. apply some solder to the solder tip of the soldering iron
- 5. Put tip to wire in solder cup.
- 6. After 1 seconds bring in the solder
- 7. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



	F 3	HOW5	HAND					tolerance			scale: 5:1
	ED OR AY NOT WITHOU	בֿן כֿ כ								T .	material: SEE SHEET 1
		CONEC	<u>ہ</u> ل							dim. in mm	
E COPIED	# < > (3 9	2						date	name	title:
		2 3	DKAWING					drawn	16.09.2015	Heinrich	RECOMMENDED PANEL CUT-OUT
	WAY, /	2 2						appd.	22.09.2015	Fischer	D-SUB FEMALE 15pos. SOLDER CUP
	NY NO ION.	COPYKIGH	3 5					norm			with open 4-40 UNC thread
2	₹ 5 5 5 6 5 6 5 6 5 6 5 6 5 6 6 6 6 6 6							d-old			dwg no: DIN-
		1 2	AL EK					_	45 =.		15K1A1671
	DRA ODU ASSE TEN		<u> </u>	а	Original			CON		sh: 2	
	REPR BE PA WRIT			rev.	description	date	name	7			part no: SEE SHEET 1