


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 50 Watt max. and use a pencil tip.
- 4. Apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 second bring in solder.
- 7. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



	r JUT GmbH	HAND					tol	erance		scale: 4:1
	ED OR AY NOT WITHOU	[₹								material: SEE SHEET 1
	IED OR MAY NO- Y WITHC	B√							dim. in mm	
E COPIE AND M. PARTY		9						date	name	title:
	E CO AND PAR T O	<					drawn	29.09.14	Lehmenkühler	RECOMMENDED PANEL CUT-OUT
	- {A R } }						appd.	26.01.15	Fischer	D-SUB FEMALE 25pos. SOLDER CUP
	NY NO A TH ION.	GAD I					norm			with open 4-40 UNC thread
	M N N N N N N N N N N N N N N N N N N N						d-old			dwg no: DIN-
	WIN CEC PER	∀	1 x c	Ä5827	25.09.15	Unkrüer	_	45 =		15K1A1544
	HIS DRA EPRODU E PASSE VRITTEN	NOT	а	Original 15KT	sh: 2					
	HIS EPR EPA ARIT	0	rev.	description	date	name	7		11-	part no: SEE SHEET 1